'25MAY21 PM 2:24 CITY CLERK

HONOLULU FIRE DEPARTMENT
KA 'OIHANA KINAI AHI O HONOLULU
CITY AND COUNTY OF HONOLULU

636 SOUTH STREET • HONOLULU, HAWAI'I 96813
PHONE: (808) 723-7139 • FAX: (808) 723-7111 • WEBSITE: honolulu.gov

RICK BLANGIARDI
MAYOR
MEIA

SHELDON K. HAO
FIRE CHIEF
LUNA NUI KINAI AHI

JASON SAMALA
DEPUTY FIRE CHIEF
HOPE LUNA NUI KINAI AHI

May 20, 2025

The Honorable Tommy Waters
Chair and Presiding Officer
and Members
Honolulu City Council
530 South King Street, Room 202
Honolulu, Hawai'i 96813

Dear Chair Waters and Councilmembers:

SUBJECT: Annual Report Pursuant to Ordinance 22-02
Relating to Fire Safety

As a follow-up to Section 7 of the abovementioned ordinance, the Honolulu Fire Department (HFD) provides the following:

(a) *Information on the status of a building's Life Safety Evaluation ("LSE") scores in the six categories listed in Section 4: Mobility Status, Vertical Openings, Standpipe System - Class 1 Standpipe, Elevators - Emergency Power, Egress Routes - Compliant Stairwell Reentry, and Table 8.*

The HFD received a cumulative count of 303 building fire and LSE from licensed design professionals (LDP) for buildings identified on the attachment. Of the 303 LSEs, 30 received an acceptable level of fire safety.

The attachment lists the buildings and their associated scores in each of the six categories and Table 8.

(b) *A list of any buildings that are being added to the attachment to Ordinance 19-4 marked as Exhibit B and the criteria for the addition of the buildings.*

No additional buildings were added to Exhibit B since the last report dated November 25, 2024.

(c) *A list of any buildings that are being removed from the attachment to Ordinance 19-4 marked as Exhibit B and the criteria for the removal of the buildings.*

A total of 68 buildings provided documentation verifying they did not meet the definition of a high-rise residential building. Since the previous Three-Month Report dated November 25, 2024, one building provided documentation verifying they did not meet the definition of a high-rise residential building and was removed from the list:

Pacific Palms	Less than 75 feet

(d) *The number of appeals from AHJ [authority having jurisdiction] determinations that the level of fire safety for a building is unacceptable.*

There have been no appeals resulting from AHJ determinations.

(e) *The number of buildings that have submitted LSEs to the AHJ and the status of the buildings' progress in completing the LSE to achieve an "acceptable" score.*

The HFD received a cumulative count of 303 buildings that have submitted LSEs. A total of 273 buildings are working with their LDP to achieve an acceptable score, and 30 buildings have an acceptable score.

(f) *The number of Honolulu Fire Department ("HFD") outreach and training meetings conducted with design professionals and association of apartment owners representatives.*

The HFD conducted a cumulative count of 40 outreach and training meetings.

(g) *The number of HFD citations or inspections undertaken in relation to areas in which association of apartment owners organizations are not in compliance with the City's Fire Code.*

There were 312 inspections conducted of which 143 of these buildings were not in compliance with the Fire Code of the City and County of Honolulu.

(h) *A list of buildings that have provided the AHJ with their building fire emergency plan that includes a listing and contact information of their frail and vulnerable residents who may require evacuation assistance in an emergency.*

No additional buildings have provided their fire evacuation emergency plans since November 25, 2024.

Should you have questions, please contact Assistant Chief Craig Uchimura of our Support Services division at 808-723-7105 or cuchimura@honolulu.gov.

Sincerely,

Digitally signed by Hao, Sheldon K
Date: 2025.05.20 13:57:08 -10'00'

SHELDON K. HAO
Fire Chief

Attachment

APPROVED:

Michael D. Formby, Managing Director
Office of the Managing Director

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
1001 WILDER	2.5	3	-10	0	4	3	N	
1010 WILDER 2-4-031-002	1.5	1.6	0	5	4	-8	Y	
1011 PROSPECT	1.2	1.5	-14	0	-5	3	N	
1013 PROSPECT	2.5	3	-14	0	-5	3	N	
1040 KINAU	1.5	1.6	-14	5	0	3	N	
1073 KINAU	2.5	3	-14	5	0	0	N	
1111 WILDER AVE	1.5	1.6	-14	5	-5	-8	N	
1112 KINAU 2-4-012-012	2.5	3	-14	0	0	0	N	
1134 KINAU 2-4-012-010	2.5	3	-14	0	0	0	N	
1350 ALA MOANA	1.5	1.6	-14	5	3	1	N	
1616 LIHOLIHO	2.5	3	-14	0	0	3	N	
1628 KEEAUMOKU ST								
2033 NUUANU	2.5	3	2	0	4	3	N	
2121 ALA WAI	2.5	3	-14	5	4	0	N	
2233 ALA WAI 2-6-020-053	1.5	1.6	-10	0	-5	3	N	
250 OHUA	1.5	1.6	-14	0	0	3	N	
3003 KALAKAUA	2.5	3	-14	0	4	-8	N	
3019 KALAKAUA	2.5	3	-14	5	0	0	N	
435 WALINA APARTMENTS 2-6-021-050	2.5	3	-14	5	0	-2	N	
845 UNIVERSITY	1.5	1.6	2	0	0	3	Y	
965 PROSPECT	2.5	3	2	0	-5	0	N	
999 WILDER	2.5	3	-14	0	4	3	N	Y
ACADEMY TOWER	2.5	3	-14	5	-5	-8	N	
ALA MOANA TOWER 2-3-041-011	2.5	3	-10	0	4	0	N	
ALA WAI COVE 2-7-013-011	1.5	1.6	-14	0	0	3	N	
ALA WAI EAST	2.5	3	-14	5	0	-8	N	
ALA WAI MANOR	2.5	3	-14	0	-5	3	N	
ALA WAI MANSION	1.5	1.6	0	0	-5	-2	N	
ALA WAI PALMS 2-6-021-110	1.5	1.6	-14	0	0	-2	N	
ALA WAI PLAZA - ALA WAI TOWER	2.5	3	-14	5	-5	3	N	
ALA WAI PLAZA - DIAMOND HEAD TOWER	2.5	3	-14	5	-5	3	N	
ALA WAI SKYRISE 2-7-013-008	1.5	1.6	0	0	4	3	Y	
ALA WAI TOWNHOUSE	2.5	3	-14	0	-5	0	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
ALA WAILANI 2-6-028-037	2.5	3	0	0	-5	0	N	
ALEXANDER ARMS	2.5	3	0	5	0	3	Y	
ALOHA LANI	2.5	3	0	5	0	0	Y	
ALOHA TOWER I	2.5	3	-14	0	0	-2	N	
ALOHA TOWER II	2.5	3	-14	5	0	-8	N	
ANGA-ROA	2.5	3	-14	5	0	-8	N	
ATKINSON PLAZA	2.5	3	-10	6	-5	3	N	
ATKINSON TOWERS 2-3-036-038	2.5	3	-14	0	-5	-2	N	
BANYAN TREE PLAZA	2.5	3	-10	0	4	-2	N	
BELLEVUE TOWER	2.5	3	-14	0	-5	-8	N	
BIG SURF CONDOS	1.5	1.6	-14	5	-5	-8	N	
BOULEVARD TOWERS	1.5	1.6	-14	0	0	-2	N	
CANAL HOUSE 2-6-028-001	2.5	3	-14	5	0	0	N	
CANTERBURY PLACE	1.5	1.6	2	5	4	3	N	
CATHEDRAL POINT- BUILDING C	2.5	3	0	5	-5	3	N	
CATHEDRAL POINT- BUILDING D	2.5	3	0	5	-5	3	N	
CENTRE COURT 9-9-064-025	2.5	3	-14	5	0	3	N	
CENTURY CENTER	1.5	1.6	-14	5	4	3	N	
CENTURY WEST	1.5	1.6	0	5	0	-2	N	
CHATEAU WAIKIKI 2-6-012-029	1.5	1.6	0	5	4	3	Y	
COLONNADE ON THE GREEN - BUILDING 2 9-8-011-042	2.5	3	-14	5	-5	3	N	
COLONNADE ON THE GREEN - BUILDING 4	2.5	3	-14	5	-5	3	N	
COLONNADE ON THE GREEN - BUILDING 5	2.5	3	-14	5	-5	3	N	
COLONY SURF	1.5	1.6	-14	-5	3	1	N	
CORAL STRAND APARTMENTS	2.5	3	-10	0	0	3	N	
CORAL TERRACE	1.5	1.6	-14	7	-5	0	N	
COTY TOWER	2.5	3	-14	0	0	-2	N	
CRESCENT PARK	2.5	3	-10	0	-5	3	N	
CROWN THURSTON	2.5	3	-14	0	-5	-2	N	
DIAMOND HEAD APARTMENTS	2.5	3	-14	5	0	-8	N	
DIAMOND HEAD VISTA	1.5	1.6	-14	5	0	1	N	
DISCOVERY BAY	1.5	1.6	-14	0	4	3	N	
DOMINIS WEST	1.5	1.6	-14	5	0	0	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
DYNASTY TOWER 1-1-062-042	2.5	3	-14	0	0	3	N	
EDEN GARDENS I	2.5	3	-14	5	0	-2	N	
FAIRWAY GARDENS	1.5	1.6	-10	0	-5	-2	N	
FAIRWAY MANOR	2.5	3	-14	0	0	-2	N	
FAIRWAY VILLA	1.5	1.6	-14	5	3	0	N	
FIVE REGENTS	2.5	3	-14	5	4	-8	N	
FOSTER TOWERS - RESIDENTIAL TOWER	2.5	3	-14	0	-5	-8	N	
FOUR FOURTY FOUR 2-6-021-049	1.5	1.6	0	5	0	3	Y	
FOUR PADDLE CONDOMINIUM	2.5	3	-14	5	-5	-2	N	
GOVERNOR CLEGHORN 2-6-024-097	2.5	3	-14	0	-5	-2	N	
GREENVIEW	1.5	1.6	2	5	-5	3	Y	
GREENWOOD	1.5	1.6	0	5	-5	3	N	
H & M (A) APARTMENTS								Y
H & M APARTMENTS								Y
HAIKU HALE - BUILDING C	1.5	1.6	-14	5	4	0	N	
HALAWA VIEW APARTMENTS - BUILDING A	2.5	3	-14	0	4	0	N	
HALE ANAOLE BLDG A	2.5	3	0	5	0	3	N	
HALE KULANUI	1.5	1.6	0	5	0	3	Y	
HALE LUANA	1.5	1.6	-14	5	0	-2	N	
HALE MOANI	2.5	3	-14	5	0	3	N	
HALE O KALANI TOWERS	2.5	3	-14	0	0	0	N	
HALE O PUMEHANA	2.5	3	0	5	0	3	N	
HARBOR SQUARE-HARBORTOWER	2.5	3	-14	0	-5	-2	N	
HARBOR SQUARE-TOWN TOWER	2.5	3	-14	0	-5	-2	N	
HARBOR VIEW PLAZA	2.5	3	0	0	0	3	N	
HARBOUR RIDGE	2.5	3	-14	5	4	3	N	
HAWAIIAN CROWN APARTMENTS	2.5	3	-14	0	-5	3	N	
HAWAIIAN PRINCESS AT MAKAHA	2.5	3	-14	5	-5	-2	N	
HERITAGE HOUSE - RESIDENTIAL	1.5	1.6	-14	5	4	3	N	
HOLIDAY LAKEVIEW 1-1-058-013	2.5	3	0	0	-5	0	N	
HOLIDAY MANOR	1.5	1.6	-14	0	0	3	N	
HOLIDAY VILLAGE	2.5	3	-14	0	0	0	N	
HONO HALE TOWERS - BUILDING A	2.5	3	-14	0	0	3	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
HONO HALE TOWERS - BUILDING B	2.5	3	-14	0	0	3	N	
HONO HALE TOWERS - BUILDING C	2.5	3	-14	0	0	-8	N	
ILANIWAI	2.5	3	-14	5	0	3	N	
ILIKAI MARINA APARTMENT BUILDING	1.5	1.6	-14	5	4	3	N	
JASON APARTMENTS	2.5	3	-14	5	0	0	N	
KA HALE MOI I	2.5	3	2	0	-5	-2	N	
KAAHUMANU PLAZA 2-4-012-011	2.5	3	0	0	-5	3	N	
KAHALA TOWERS - BUILDING A 3-5-017-004	2.5	3	-14	5	4	3	N	
KAHALA TOWERS - BUILDING B 3-5-017-004	2.5	3	-14	5	4	3	N	
KAHANA KAI 1-1-061-020	2.5	3	-14	0	0	3	N	
KAILANI	2.5	3	-10	0	0	3	N	
KAIMANA LANAIS	2.5	3	-10	0	4	3	N	
KAIMANA VILLA								Y
KAIMUKI JADE 3-2-005-023	2.5	3	0	0	-5	3	N	
KAIOLU SUNRISE	1.5	1.6	2	0	4	3	N	
KALAKAUA HOMES	1.5	3	2	5	4	3	Y	
KALAKAUA SANDS	2.5	3	-14	0	-5	3	N	
KALANIHUIA BUILDING	2.5	3	2	5	4	3	Y	
KAPIOLANI BEL-AIRE	1.5	1.6	-14	0	4	0	N	Y
KAPIOLANI GARDENS	2.5	3	2	5	0	3	N	
KAPIOLANI MANOR	2.5	3	-14	5	0	-2	N	
KAPIOLANI ROYALE	2.5	3	0	0	0	3	N	
KAPIOLANI TERRACE 2-3-017-013	1.5	1.6	2	5	0	3	Y	
KAPIOLANI TOWERS	1.5	1.6	2	0	0	3	N	
KAPIOLANI TOWN HOUSE 2-3-019-065	2.5	3	-14	-5	-5	-2	N	
KAUHALE CONDOS	2.5	3	-14	0	0	0	N	
KAULUWELA 1	2.5	3	-14	0	4	3	N	
KEALANI CONDOMINIUM	1.5	1.6	-14	-10	0	3	N	
KEMOO BY THE LAKE	2.5	3	-14	5	0	3	N	
KEOLA HOONANEA	2.5	3	0	0	0	3	Y	
KEONI ANA APARTMENTS	2.5	3	-10	5	0	-2	N	
KINAU LANAIS 2-1-040-003	2.5	3	-14	0	0	3	N	
KINAU VILLA - BUILDING D 2-1-041-024	1.5	1.6	2	-5	0	0	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
KING KALANI	2.5	3	-10	0	0	0	N	
KING MANOR 2-1-042-001	1.5	1.6	-14	0	0	-2	N	
KING TERRACE								
KUHIO AT WAIKIKI	2.5	3	-14	0	4	3	N	
KUHIO PLAZA	2.5	3	-10	0	0	-2	N	
KUKUI PLAZA - DIAMOND HEAD TOWER	2.5	1.6	0	5	4	3	Y	
KUKUI PLAZA - EWA TOWER	2.5	1.6	0	5	4	3	Y	
LA CASA 2-6-016-009	1.5	1.6	0	5	-5	3	N	
LAKE VIEW ROYAL	2.5	3	-14	0	0	3	N	
LAKESHORE TOWER	2.5	3	-14	0	-5	-2	N	
LAKESIDE MANOR	2.5	3	-14	5	-5	3	N	
LAKESIDE WEST	2.5	3	-14	0	-5	-2	N	
LAKEVIEW GARDENS	2.5	3	0	0	0	3	Y	
LAKEVIEW SANDS	2.5	3	-10	5	0	-8	N	
LAKEVIEW TERRACE	2.5	3	-14	5	0	-8	N	
LEHUA MANOR								Y
LEISURE HERITAGE	1.5	1.6	-14	0	-5	0	N	
LELE PONO CONDOMINIUM	2.5	3	-14	5	4	3	N	
LILIHA SQUARE	2.5	3	-10	5	0	-2	N	
LILIUOKALANI PLAZA	1.5	1.6	-14	7	0	3	N	
LIME TREE	2.5	3	-14	5	-5	3	N	
LUNA-LIHO TOWERS	1.5	1.6	-10	6	0	3	N	
LUNALILO TOWER	1.5	1.6	-14	0	4	-2	N	
MAKAHA VALLEY TOWERS - CORE 1	2.5	3	0	5	4	3	Y	
MAKAHA VALLEY TOWERS - CORE 2	2.5	3	0	5	4	3	Y	
MAKAHA VALLEY TOWERS - CORE 3	2.5	3	0	5	4	3	Y	
MAKAHA VALLEY TOWERS - CORE 4	2.5	3	0	5	4	3	Y	
MAKEE AILANA	2.5	3	0	0	0	3	Y	
MAKIKI MANOR	2.5	3	-10	5	-5	-8	N	
MAKIKI PLAZA	1.5	1.6	2	5	0	3	Y	
MAKIKI REGENT								
MAKIKI ROYAL	2.5	3	0	0	0	-2	N	
MAKIKI TOWERS	2.5	3	-14	0	0	3	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
MAKIKILANI PLAZA	1.5	1.6	2	5	0	0	Y	
MAKINI AT KINAU	2.5	3	-14	0	0	3	N	
MAKUA ALII	2.5	3	2	5	4	3	Y	
MALULANI HALE	2.5	3	0	5	-5	1	N	
MANOALANI APARTMENTS	2.5	3	-14	0	0	3	N	
MARCO POLO								
MARINA TOWERS	1.5	1.6	0	0	-5	3	Y	
MATLOCK HALE 2-4-011-056	2.5	3	0	5	-5	-2	N	
MAUNA LUAN EAST	1.5	1.6	2	5	4	3	N	
MAUNA LUAN WEST	1.5	1.6	2	5	4	3	N	
MAUNAIHI TERRACE	2.5	3	-14	0	0	3	N	
MCCULLY VILLA	2.5	3	-14	5	4	0	N	
MERIDIAN EAST 4-3-054-013	2.5	3	0	0	0	3	Y	
MONTE VISTA 2-6-024-079	2.5	3	-14	0	0	3	N	
MOTT-SMITH LANILOA	1.5	1.6	-14	5	4	3	N	
MOUNT TERRACE	1.5	1.6	-14	5	4	-2	N	
NANIWA GARDENS 3-9-070-002	2.5	3	-14	5	0	-8	N	
NAPILI TOWERS	2.5	3	-14	0	-5	-2	N	
NORTHBROOK - BUILDING D	2.5	3	-14	-10	0	3	N	
NUUANU BROOKSIDE 2-2-010-035	2.5	3	-14	5	0	0	N	
NUUANU TOWERS	2.5	3	0	5	0	-8	N	
OAHU SURF ONE 2-6-015-026	2.5	3	-14	0	-5	3	N	
OAHU SURF TWO	2.5	3	-14	0	0	3	N	
OAHUAN TOWER	2.5	3	-14	0	0	3	N	
OHUALANI	2.5	3	-14	5	-5	-8	N	
PACIFIC GRAND	2.5	3	-14	0	4	0	N	
PACIFIC INTERNATIONAL 2-6-025-040	2.5	3	-14	0	0	0	N	
PACIFIC MANOR	2.5	3	-14	0	0	3	N	
PACIFICANA APARTMENTS	2.5	3	-14	0	0	3	N	
PAKALANA	1.5	1.6	-14	0	0	3	N	
PALMS OF KILANI	1.5	1.5	-10	0	0	0	N	
PALO ALTO	2.5	3	2	0	0	0	Y	
PAOAKALANI TOWER	2.5	3	2	5	4	0	Y	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
PARKLAND GARDENS	2.5	3	-10	0	4	3	N	
PARKVIEW	2.5	3	-14	0	0	3	N	
PEARL ONE	2.5	3	-14	5	0	3	N	
PEARL TWO 9-8-039-013	1.5	1.6	-14	5	4	3	N	
PEARLRIDGE GARDENS AND TOWER - BLDG 7	1.5	1.6	-14	5	0	3	N	
PEARLRIDGE SQUARE	2.5	3	-14	5	0	-8	N	
PIIKOI PLAZA	2.5	3	-14	0	0	-2	N	
PIIKOI TOWER	2.5	3	-14	5	0	3	N	
PIKAKE MANOR	2.5	3	-14	5	0	3	N	
PLAZA AT HAWAII KAI 3-9-070-001	1.5	1.6	-14	5	-5	-2	N	
PLEASANTON 2-4-023-013	2.5	3	0	0	0	3	N	
PLUMERIA HALE 2-7-018-036	2.5	3	-14	5	0	0	N	
POHAI NANI	2.5	3	-14	0	4	-2	N	
POMAIKAI 2-6-012-007	2.5	3	-14	5	0	-8	N	
PRINCESS KEALOHA 2-4-025-039	2.5	3	-14	0	0	3	N	
PRINCESS LEILANI	2.5	3	-14	5	0	0	N	
PROSPECT TOWER	1.5	1.6	-14	0	0	3	N	
PULELEHUA	2.5	3	-14	0	0	-2	N	
PUMEHANA APARTMENTS	2.5	3	2	5	4	3	N	Y
PUNAHOU CHALET	2.5	3	-14	5	0	3	N	
PUNAHOU CIRCLE APARTMENTS	2.5	3	-14	0	0	3	N	
PUNAHOU GARDENS 2-4-023-033	2.5	3	-14	0	0	3	N	
PUNAHOU MANOR 2-4-023-005	2.5	3	-14	0	0	0	N	Y
PUNAHOU ROYALE	2.5	3	-14	5	0	3	N	
PUNAHOU SUNSET	2.5	3	-14	0	0	3	N	
PUNAHOU TOWER 2-8-012-036	2.5	3	-14	2	0	0	N	
PUNAHOU VISTA	2.5	3	-14	5	0	-8	N	
QUEEN EMMA GARDENS KING TOWER	1.5	1.6	2	0	4	-8	N	
QUEEN EMMA GARDENS PRINCE TOWER	1.5	1.6	2	0	4	-8	N	
QUEEN EMMA GARDENS QUEEN TOWER	1.5	1.6	2	0	4	-8	N	
RAINBOW PLACE	2.5	3	-14	5	0	0	N	
REGENCY AT KAHALA	1.5	1.6	-14	0	4	3	N	
REGENCY TOWER 2-7-019-015	2.5	3	-14	0	0	-8	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
ROSALEI 2-6-017-004	2.5	3	0	0	0	-2	N	
ROSE TERRACE 2-4-030-075	2.5	3	-10	0	-5	3	N	
ROYAL ALOHA CONDOMINIUM	2.5	3	-14	5	-5	3	N	
ROYAL COURT 2-1-044-033	2.5	3	-14	0	0	3	N	
ROYAL KUHIO CONDO	2.5	3	0	0	4	3	N	
ROYAL TOWERS	2.5	3	0	5	-5	3	N	
ROYAL VISTA								Y
SAKURA	2.5	3	0	5	0	3	N	
SANS SOUCI	2.5	3	-10	0	4	-2	N	
SCANDIA TOWERS 2-6-027-026	2.5	3	-14	0	0	3	N	
SCENIC TOWER	2.5	3	-14	5	0	-2	N	
SEABREEZE 3-1-033-059	2.5	3	-14	5	0	-8	N	
SEASIDE SUITES	2.5	3	-10	5	0	0	N	
SEASIDE TOWERS CONDO	2.5	3	-14	0	0	-2	N	
SEVENTEEN SEVENTEEN ALA WAI	1.5	1.6	0	0	4	3	N	
SKY TOWER	2.5	3	-10	0	-5	3	N	
SUMMER PALACE	2.5	3	-14	5	-5	0	N	
SUMMER VILLA	2.5	3	-14	5	0	3	N	
SUNSET LAKEVIEW - BUILDING A 1-1-060-012	1.5	1.6	-14	0	-5	3	N	
SUNSET LAKEVIEW - BUILDING B 1-1-060-012	1.5	1.6	-14	0	-5	3	N	
SUNSET TOWERS	2.5	3	-10	0	0	3	N	
TERRACE TOWERS 2-7-015-004	1.5	1.6	-14	0	0	3	N	
THE ALEXANDER	2.5	3	-10	0	-5	3	N	
THE ALIKA	2.5	3	-14	5	0	0	N	
THE BARCLAY	1.5	1.6	-14	0	0	3	N	
THE BEL AIRE 2-6-015-035	2.5	3	-14	0	0	-2	N	
THE CAMELOT	1.5	1.6	-14	0	0	3	N	
THE CONSULATE	2.5	3	0	0	0	3	N	
THE CONTESSA	1.5	1.6	-14	0	0	3	N	
THE CORONET 2-4-014-052	2.5	3	-14	0	0	0	N	
THE HAUSTEN 2-7-010-036	2.5	3	-14	5	0	3	N	
THE HIGHLANDER 9-8-012-054	2.5	3	-14	5	0	3	N	
THE KALIA - BUILDING A	1.5	1.6	-14	0	0	3	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
THE KALIA - BUILDING B	1.5	1.6	-14	0	0	3	N	
THE KALIA - BUILDING C	1.5	1.6	-14	0	0	-8	N	
THE KAMAAINA 2-1-039-002	2.5	3	-14	0	0	3	N	
THE MAGELLAN	1.5	1.6	0	0	-5	3	Y	
THE MAILE TOWER	2.5	3	-14	5	0	-8	N	
THE NIIHAU	2.5	3	-10	0	0	-8	N	
THE PALMS CONDOMINIUM 2-6-021-020	2.5	3	0	5	4	-2	N	
THE PAVILION AT WAIKIKI	1.5	1.6	-10	0	0	3	N	
THE SANDALWOOD	2.5	3	-14	0	0	3	N	
THE SEASHORE	1.5	1.6	2	5	0	3	N	
THE SURFVIEW	2.5	3	-14	0	-5	3	N	
THE TOWERS AT KUHIO PARK - TOWER A	2.5	3	0	0	4	3	N	
THE TOWERS AT KUHIO PARK - TOWER B	2.5	3	0	0	4	3	N	
THE TOWN HOUSE 2-4-017-056	2.5	3	-14	0	0	-2	N	
THE VILLA ON EATON SQUARE	2.5	3	-14	5	4	3	N	
THE WOODROSE	2.5	3	-14	0	0	-2	N	
TRADEWINDS HOTEL - BUILDING A	2.5	3	-14	0	-5	-8	N	
TRADEWINDS HOTEL - BUILDING B	2.5	3	-14	0	-5	-8	N	
TRADEWINDS PLAZA	2.5	3	2	5	0	3	N	
TROPIC SEAS - BUILDING A	2.5	3	-14	0	0	-2	N	
TWIN TOWERS	2.5	3	-14	0	0	-2	N	
UNIVERSITY VILLA	2.5	3	-14	5	0	0	N	
VICTORIA MANSION A	2.5	3	-14	0	0	3	N	
VICTORIA PLAZA	2.5	3	0	0	-5	-2	N	
VICTORIA TOWERS	2.5	3	-14	5	-5	3	N	
VILLAGE MALUHIA	2.5	3	-10	0	0	3	N	
WAIKALANI WOODLANDS - BUILDING A	2.5	3	-14	5	0	3	N	
WAIKALANI WOODLANDS - BUILDING B	2.5	3	-14	5	0	3	N	
WAIKALANI WOODLANDS - BUILDING C	2.5	3	-14	5	0	3	N	
WAIKALANI WOODLANDS - BUILDING D	2.5	3	-14	5	0	3	N	
WAIKELE TOWERS	1.5	1.6	-10	0	0	0	N	
WAIKIKI IMPERIAL APARTMENTS	2.5	3	0	0	-5	3	N	
WAIKIKI LANAIS	1.5	1.6	2	0	4	3	N	

NAME	Mobility Status Enter (O1)	Mobility Status Enter (FF1)	(LSER) Value for VERTICAL OPENINGS (Low -10, Lowest -14)	(LSER) Value for STANDPIPE SYSTEM (Low 0, Lowest -10)	(LSER) Elevators (Lowest -5)	(LSER) Egress Routes (Lowest -8)	Table 8 Level of fire safety is acceptable	Table 8 Compliance will be met with an automatic sprinkler system
WAIKIKI PARK HEIGHTS	2.5	3	0	5	-5	3	N	
WAIKIKI SHORE APARTMENTS	1.5	1.6	-10	0	0	-2	N	
WAIKIKI SKYLINER	2.5	3	-10	0	0	3	N	
WAIKIKI SKYTOWER 2-6-024-053	2.5	3	2	0	4	3	N	
WAIKIKI TOWNHOUSE	2.5	3	-14	5	4	-8	N	
WAIKIKI WALINA APARTMENTS 2-6-021-018	2.5	3	-14	5	0	-2	N	
WAILANA AT WAIKIKI	2.5	3	-10	5	0	-2	N	
WAIPUNA 2-6-013-002	2.5	3	-14	5	-5	0	N	
WARD KINAU	2.5	3	0	5	0	3	Y	
WILDER AT PIIKOI-TOWER	2.5	3	-14	5	0	3	N	
WILDER REGENT	2.5	3	-14	5	0	-2	N	
WILDER TERRACE	2.5	3	-14	0	-5	3	N	
WILDER TOWER	2.5	3	-14	5	0	-8	N	
YACHT HARBOR TOWERS - DIAMOND HEAD TOWER	1.5	1.6	-14	0	4	-2	N	
YACHT HARBOR TOWERS - EWA TOWER	1.5	1.6	-14	0	4	-2	N	